



Raychem

3SC-4PT 3SC- 6PT 3SC-8PT

Power Connection Kit Installation Instructions





APPROVALS

Hazardous Locations



Class I, Div. 2, Groups B, C, D
Class II, Div. 2, Groups F, G
Class III



Class I, Div. 2, Groups A, B, C, D
Class II, Div. 2, Groups F, G
Class III

For T-Rating, see design documentation

DESCRIPTION

The Raychem 3SC-4PT, 3SC-6PT, and 3SC-8PT are NEMA 4 rated power connection kits designed for use with Raychem 3SC60, 70, 80 (-CT), 3SC/H60, 70, 80 (-CT) and 3SC/F60, 70, 80 (-CR) series heating cables in hazardous locations.

This kit may be installed at temperatures as low as -40°F (-40°C). For easier installation, store above freezing until just before installation.

For technical support, call Chemelex at (800) 545-6358.

TOOLS REQUIRED

- Slotted screwdriver
 - Wire strippers
 - Diagonal cutters
 - Utility knife
 - Disposable towel or rag
 - Adjustable wrench
 - Solder tool or torch (with small tip)
 - Thomas & Betts TBM5S crimp tool or equivalent (P/N P000000585)
 - Thomas & Betts WT2000 crimp tool or equivalent (P/N 273435-000)
- Crimp tools can be ordered from Chemelex

ADDITIONAL MATERIALS REQUIRED

- Glass cloth tape:
 - GT-66 for installation temperature above 40°F (4°C)
 - GS-54 for installation temperature above -40°F (-40°C)
- Agency approved junction box suitable for the area classification
- Circuit identification tag (P/N P000000311)

⚠ WARNING:

This component is an electrical device that must be installed correctly to ensure proper operation and to prevent shock or fire. Read these important warnings and carefully follow all of the installation instructions.

- To minimize the danger of fire from sustained electrical arcing if the heating cable is damaged or improperly installed, and to comply with the requirements of Chemelex, agency certifications, and national electrical codes, ground-fault equipment protection must be used. Arcing may not be stopped by conventional circuit breakers.
- Component approvals and performance are based on the use of Chemelex-specified parts only. Do not use substitute parts or vinyl electrical tape.
- Damaged conductors can overheat or short. Do not break conductor wire strands when scoring the jacket or removing insulation.
- Keep components and heating cable ends dry before and during installation.
- Use only fire-resistant insulation materials, such as fiberglass wrap or flame-retardant foam.
- Soldering tools or torches can cause fire or explosion in hazardous areas. Be sure there are no flammable materials or vapors in the area before using these tools.
- Wrap exposed conductors with supplied tape strips to prevent shorts.

⚠ CAUTION:

Health Hazard: Hot solder can burn eyes and skin. Fumes during soldering are irritating to eyes and may cause headache and respiratory system irritation or damage. Prolonged or repeated exposure to rosin flux fumes during soldering may result in allergic reaction in a sensitive person, resulting in asthma symptoms. Consult MSDS VEN0043 for further information.


Silicone rubber compound Part A and Part B may generate flammable and explosive hydrogen gas if it comes in contact with an acidic, basic or oxidizing material. Personal contact with the silicone rubber compound may cause slight eye or skin irritation. Consult MSDS VEN0030 and VEN0031 for further information.

CHEMTREC 24-hour emergency telephone:
(800) 424-9300

Non-emergency health and safety information:
(800) 545-6258.

KIT CONTENTS:


Item	Qty	Description
A	1	Box with cover, gasket, and 2 screws
B	1	Bushing
C	2	Grommets
D	22	Tape strips (19 required, 3 extra)
E	1	Pipe clamp banding kit
F	1	Armor assembly
G	3	Cold leads
H	2	Cable lubricants
I	1	Ring terminal, bolt, lock washer, and nut
J	1	Teflon® tape
K	3	Coils of Kester® 48 core LF solder for nickel
L	4	Compression joints (see table in Step 7), spare included
M	1	KE 1204 silicone rubber potting compound Part A
N	1	KE 1204 silicone rubber potting compound Part B
O	2	Stir sticks
P	2	Material Safety Data Sheets (not shown)



Heating cable construction

Heating cable types

3SC60, 70 and 80 (-CT)
 3SC/H60, 70 and 80 (-CT)
 3SC/F60, 70 and 80 (-CR)




1

- Allow approximately 18 inches (46 cm) of heating cable for installation.






18 in.
(46 cm)

2

- For easier installation apply cable lubricant inside grommet from each end.
- Insert the heating cable into the bushing and grommet as shown.



- Position box on the heating cable as shown.



8

WARNING: Using the wrong splice can cause overheating. Use only the splice specified for the cable type.

Heating cable ⁽¹⁾	Heating cable conductor size	Power connection kit	Power connection wire size	Thomas & Betts (T&B)	
				Splice catalog no.	Die and splice color
3SC60-CT	12 AWG	SC-8PT	8 AWG	54610	Blue
3SC70-CT	10 AWG	SC-6PT	6 AWG	54615	Gray
3SC80-CT	8 AWG	SC-4PT	4 AWG	54625-TB	Green

⁽¹⁾ The above table is also applicable for 3SC/H60, 70, 80 (-CT) and 3SC/F60, 70, 80 (-CR) heating cables.

For replacement crimps, call Chemelex at (800) 545-6258.

- Overlap conductors in splice.

- Crimp cold leads to heating cable conductors. Using the specified crimp tool, die and splices to ensure proper electrical connection (see table). Improperly crimped connections can result in overheating.

- Smooth down any sharp wires after crimping to prevent wires from poking through tape in Step 10.

9

WARNING: Fire and Health Hazard

Soldering tools or minitorches can cause fire or explosion in hazardous areas. Be sure there are no flammable materials or vapors in the area before using these tools. Follow all site safety guidelines when working in hazardous areas.

Refer to solder material safety data sheet packaged with kit.


Do not overheat or char the conductor insulation. Inhalation of fumes can cause polymer fume fever, flu-like symptoms, irritation, and difficulty breathing.





- Use only solder provided with kit. Only Kester 48 core LF has been qualified with SC cables.
- Heat each splice using a soldering tool, or a propane or MAPP gas torch.
Note: MAPP gas may be required if the connections are being soldered at temperatures below -4°F (-20°C). Heat the center of the splice until it is hot enough to melt the solder placed at both ends. Allow the connections to cool before proceeding to the next step.




10

IMPORTANT: To ensure proper electrical insulation, use the specified high temperature Teflon® tape provided with the kit. Do not use common vinyl tape that does not have adequate temperature rating.

- Use release liner to guide tape while wrapping the tape strips around the connection. Use five strips of tape, covering splice and ¼-inch (6 mm) of conductor insulation (approximately three overlapped layers).
- Wrap braid with two tape strips.







North America

Tel +1 800 545 6258
info@chemelex.com

Latin America

Tel +1 713 868 4800
info@chemelex.com

Europe, Middle East, Africa, India

Tel +32 16 213 511
Fax +32 16 213 604
info@chemelex.com

Asia Pacific

Tel +86 21 2412 1688
infoAPAC@chemelex.com

chemelex
excellence is everything

Raychem

Tracer

Pyrotenax

Nuheat