

# Replacement Front Plate for Syspend Aluminum HMI Enclosure



Replacement Front Plates for Syspend Aluminum HMI Enclosure are aluminum with clear anodized brushed finish.

## FEATURES

---

Mounting hardware included

## SPECIFICATIONS

**Material:** Aluminum

**Finish:** Anodized

Table 1/1

Catalog Number	Article Number	Height	Width	Depth	Thickness	Quick Ship
SY2222AFP	34121	9.41in	9.41in	0.12in	14ga	No
SY2525AFP	34132	10.39in	10.39in	0.12in	14ga	No
SY2730AFP	34122	15.31in	12.36in	0.12in	14ga	No
SY3030AFP	34135	12.36in	12.36in	0.12in	14ga	No
SY3222AFP	34123	13.35in	9.41in	0.12in	14ga	No
SY3225AFP	34136	13.35in	10.39in	0.12in	14ga	No
SY3235AFP	34124	13.35in	14.33in	0.12in	14ga	No
SY3237AFP	34133	13.35in	15.31in	0.12in	14ga	No
SY3535AFP	34137	14.33in	14.33in	0.12in	14ga	No
SY3537AFP	34125	14.33in	15.31in	0.12in	14ga	No
SY3545AFP	34138	14.33in	18.27in	0.12in	14ga	No
SY3742AFP	34134	15.31in	17.28in	0.12in	14ga	No
SY4040AFP	34141	16.3in	16.3in	0.12in	14ga	No
SY4050AFP	34126	16.3in	20.24in	0.12in	14ga	No
SY4547AFP	34142	18.27in	19.25in	0.12in	14ga	No
SY4552AFP	34127	18.27in	21.22in	0.12in	14ga	No
SY5050AFP	34131	20.24in	20.24in	0.12in	14ga	No

Catalog Number	Article Number	Height	Width	Depth	Thickness	Quick Ship
SY5052AFP	34143	20.24in	21.22in	0.12in	14ga	No
SY6050AFP	34128	24.17in	20.24in	0.12in	14ga	No

**WARNING**

nVent products shall be installed and used only as indicated in nVent's product instruction sheets and training materials. Instruction sheets are available at [www.nvent.com](http://www.nvent.com) and from your nVent customer service representative. Improper installation, misuse, misapplication or other failure to completely follow nVent's instructions and warnings may cause product malfunction, property damage, serious bodily injury and death and/or void your warranty.



Our powerful portfolio of brands:

CADDY   ERICO   HOFFMAN   ILSCO   SCHROFF   TRACHTE