

# Varistar CP Bottom Rear Panel, Shortened

## Servicios públicos de energía

Shortened Rear Panel available for IP20, IP55 and EMC applications.

Shortened rear panels ensure efficient cable management.

### CARACTERÍSTICAS

Screw fixed, Robust and Single person mountable Side Panel

Plain or with brush strip

Height of connection plate 400 mm

### ESPECIFICACIONES

Table 1/2

| Número de catálogo | Rack Height | Altura  | Ancho  | Protection Rating | Color      | Color Code |
|--------------------|-------------|---------|--------|-------------------|------------|------------|
| 21630-354          | 38 U        | 1800 mm | 600 mm | IP55              | Black Grey | RAL 7021   |
| 21630-355          | 38 U        | 1800 mm | 800 mm | IP55              | Black Grey | RAL 7021   |
| 21630-356          | 42 U        | 2000 mm | 600 mm | IP55              | Black Grey | RAL 7021   |
| 21630-357          | 42 U        | 2000 mm | 800 mm | IP55              | Black Grey | RAL 7021   |
| 21630-358          | 47 U        | 2200 mm | 600 mm | IP55              | Black Grey | RAL 7021   |
| 21630-359          | 47 U        | 2200 mm | 800 mm | IP55              | Black Grey | RAL 7021   |

Table 2/2

| Número de catálogo | Product Type |
|--------------------|--------------|
| 21630-354          | Cabinet Door |

| Número de catálogo | Product Type |
|--------------------|--------------|
| 21630-355          | Cabinet Door |
| 21630-356          | Cabinet Door |
| 21630-357          | Cabinet Door |
| 21630-358          | Cabinet Door |
| 21630-359          | Cabinet Door |

### ADDITIONAL PRODUCT DETAILS

The height of the rear panel is 400 mm less than the cabinet height to accomodate the connecting plate.

Please purchase the grounding kit separately.

### ADVERTENCIA

Los productos nVent deben instalarse y usarse solo como se indica en las hojas de instrucciones y materiales de capacitación del producto nVent. Las hojas de instrucciones están disponibles en [www.nvent.com](http://www.nvent.com) y con su representante de atención al cliente de nVent. La instalación incorrecta, el mal uso, la aplicación incorrecta u otras fallas en el seguimiento completo de las instrucciones y advertencias de nVent pueden causar el mal funcionamiento del producto, daños a la propiedad, lesiones corporales graves y la muerte y/o anular la garantía.



Our powerful portfolio of brands:

**CADDY ERICO HOFFMAN ILSCO SCHROFF TRACHTE**