


EuropacPRO Rear Hood for Stainless Steel EMC Gasket

Servicios públicos de energía



The rear hood is used as a shielded rear boundary and requires 60 mm space. Therefore if the rear hood is used, the side panel depth must be 60 mm greater than the board depth. Contact between the rear hood and the horizontal rails is established by the stainless steel contact strip for the cover plate. Thus no additional EMC sealing is necessary. Rear hood cannot be used simultaneously with rear corner profile.

CERTIFICACIONES



CARACTERÍSTICAS

The rear hood is used as a shielded rear boundary. The rear hood requires 60 mm space. Therefore if the rear hood is used, the side panel depth must be 60 mm greater than the board depth. Example: For a board depth of 160 mm a side panel (with rear hood) of 235 mm (175 mm + 60 mm) is used

Contact between the rear hood and the horizontal rails is established by the stainless steel contact strip for the cover plate. Thus no additional EMC sealing is necessary

Rear hood cannot be used simultaneously with rear corner profile

For EMC-shielding please order EMC gasket for horizontal rail separately.

ESPECIFICACIONES

Table 1/2

Número de catálogo	Rack Height	Rack Width	Package Quantity	Product Family	Product Type	Tipo
34561-763	6 U	63 HP	1	EuropacPRO	Cubierta	Rear Hood

Número de catálogo	Rack Height	Rack Width	Package Quantity	Product Family	Product Type	Tipo
34561-752	3 U	84 HP	1	EuropacPRO	Cubierta	Rear Hood
34561-750	3 U	42 HP	1	EuropacPRO	Cubierta	Rear Hood
34561-764	6 U	84 HP	1	EuropacPRO	Cubierta	Rear Hood

Table 2/2

Número de catálogo	Works With
34561-763	Subracks
34561-752	Subracks
34561-750	Subracks
34561-764	Subracks

ADDITIONAL PRODUCT DETAILS

Required quantity of screws per rear hood: 3 U subrack 10 screws; 6 U subrack 16 screws.

ADVERTENCIA

Los productos nVent deben instalarse y usarse solo como se indica en las hojas de instrucciones y materiales de capacitación del producto nVent. Las hojas de instrucciones están disponibles en www.nvent.com y con su representante de atención al cliente de nVent. La instalación incorrecta, el mal uso, la aplicación incorrecta u otras fallas en el seguimiento completo de las instrucciones y advertencias de nVent pueden causar el mal funcionamiento del producto, daños a la propiedad, lesiones corporales graves y la muerte y/o anular la garantía.



Our powerful portfolio of brands:

CADDY ERICO HOFFMAN ILSCO SCHROFF TRACHTE